

product catalog: service data\NHTSA



DataOne Software NHTSA Recall data is filtered to

include vehicle specific items and is mapped to our vehicle identification fields. The materials are formatted to support CRM/marketing outreach programs as well as service center solutions used by vehicle technicians.

File format & Delivery: Delimited, FTP, daily updates available **Data Scope:** Consumer, and Light Duty Commercial Vehicles. US

Market Destination

Data Example: 2008 Nissan 350Z



Mfr cam#: N/A

Man. start date: 2007-05-21 Man. end date: 2007-11-08

Product mfr: Nissan North America, Inc
Report mfr: Nissan North America, Inc
Component description: Electrical System: Software
Recalled component id: 000028338000442796000001105

NHTSA recall ID: 2917 NHTSA cam#: 08V521000

Recall Type Code: V
Report received date: 2008-10-07
Record creation date: 2008-10-07
Regulation part number: N/A
Fmvvs number N/A
Recall initiator: MFR
Potential units affected: 204361
Owner notification date: 2008-11-04

Defect Summary

NISSAN IS RECALLING 204,361 MY 2007-2008 ALTIMA, ALTIMA HYBRID, 350Z, 350Z ROADSTER, MY 2008 ALTIMA COUPE, ROGUE, MY 2009 MURANO, AND INFINITI MY 2007-2008 G35 SEDAN, MY 2008 G37 COUPE AND EX35 PASSENGER VEHICLES EQUIPPED WITH CONTINENTAL AUTOMOTIVE SYSTEMS' OCCUPANT CLASSIFICATION SYSTEM (OCS) CONTROL UNITS. A VARISTOR IN THE OCS CONTROL UNIT LOCATED IN THE PASSENGER SEAT CUSHION MAY HAVE BEEN MANUFACTURED OUT OF SPECIFICATION. UNDER CERTAIN CONDITIONS, THIS COULD CAUSE AN INTERRUPTION OF SIGNAL BETWEEN THE OCS AND THE AIR BAG CONTROL UNIT (ACU).

Consequence Summary

THIS COULD RESULT IN THE PASSENGER AIR BAG BEING SUPPRESSED WHICH COULD FAIL TO PROVIDE ADEQUATE PROTECTION IN THE EVENT OF A CRASH.

Corrective Action Summary

DEALERS WILL TEST THE SIGNAL BETWEEN THE OCS AND ACU SYSTEMS USING A SPECIAL TOOL TO CHECK THAT IT IS FUNCTIONING AS DESIGNED. IF NECESSARY, THE SEAT CUSHION (CONTAINING OCS HARDWARE) WILL BE REPLACED WITH A NEW ONE MANUFACTURED TO SPECIFICATION. THE RECALL BEGAN ON NOVEMBER 4, 2008. OWNERS MAY CONTACT NISSAN AT 1-800-647-7261 OR INFINITI AT 1-800-662-6200.

Notes CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV.

© 2010 DataOne Software, division of Dominion Enterprises. All rights reserved.